

USING DATA

for Preventive Maintenance of Embraer 190/195



Vadym - Chief Engineer,
Avionics Systems




Andrey - Captain,
E190 Technical pilot

HISTORY



UR-EMA	LH HPSOV closed	AFT PAX door LKD snsr adj recom	MAU 2 GIO2A FAULT	FLAP LO RATE
12.07.2017	OK	OK	45452139CMC	OK
13.07.2017	OK	OK	45452139CMC	27530001ACE
14.07.2017	OK	OK	45452139CMC	OK
15.07.2017	OK	OK	45452139CMC	OK
16.07.2017	OK	OK	OK	OK
17.07.2017	OK	OK	OK	OK
18.07.2017	36111103AM1	OK	45452139CMC	OK
19.07.2017	OK	OK	OK	OK
20.07.2017	OK	OK	OK	OK
21.07.2017	OK	OK	OK	OK
22.07.2017	OK	OK	45452139CMC	OK
23.07.2017	OK	OK	45452139CMC	OK
24.07.2017	OK	52122111PSS (CRUISE)	OK	OK
25.07.2017	OK	52122111PSS (Cruise)	OK	OK
26.07.2017	OK	OK	OK	OK
27.07.2017	OK	OK	OK	OK
28.07.2017	OK	OK	45452139CMC	OK
29.07.2017	OK	OK	45452139CMC	OK
30.07.2017	OK	52122111PSS (Cruise)	OK	OK
31.07.2017	OK	OK	45452139CMC	OK
01.08.2017	OK	OK	OK	OK
02.08.2017	OK	OK	OK	OK
03.08.2017	OK	52122111PSS (Cruise) need	45452139CMC	27530001ACE (APPROACH)
04.08.2017	OK	OK	45452139CMC	OK
05.08.2017	OK	OK	OK	OK
06.08.2017	OK	OK	OK	OK
07.08.2017	OK	OK	OK	OK
08.08.2017	OK	OK	45452139CMC + EICAS AVNX MAU 2A FAULT	OK
09.08.2017	OK	OK	Generic I/O was replaced iaw WO 889283	OK
10.08.2017	OK	52122111PSS (Cruise)	OK	OK
11.08.2017	OK	OK	OK	OK
12.08.2017	OK	52122111PSS (Cruise)	OK	OK
13.08.2017	OK	52122111PSS (Cruise)	OK	OK
14.08.2017	OK	OK	52139CMC (may be caused by transitory condition) + EICAS AVNX MAU 2A FAULT if msg will appear one more time than continue trol	OK
15.08.2017	OK	OK	OK	OK

COST STRUCTURE



Source: IATA ACMG 2017 Annual Report

STRATEGIC KPIs



Cost Structure	FY2017 ACMG Airlines			UIA 2017
	US Cents/ASK	000\$/FH	\$/Pax	
Fuel and Oil	1.69	2.40	48.10	
Aircraft Ownership	0.91	1.29	25.80	
Maintenance and Overhaul	0.77	1.09	21.90	
Reservation, Ticketing, Sales and Promotion	0.52	0.74	14.90	
General and Administrative	0.53	0.76	15.20	
Station and Ground	0.48	0.69	13.80	
Flight Deck Crew	0.47	0.67	13.30	
Airport Charges	0.43	0.61	12.10	
Passenger Service	0.36	0.51	10.20	
Cabin Attendants	0.35	0.50	10.10	
Air Navigation Charges	0.30	0.43	8.50	
IT and Communications	0.08	0.11	2.20	
Flight Equipment Insurance	0.01	0.15	0.30	
Total	6.90	9.92	196.40	

Source: IATA ACMG 2017 Annual Report

PRIORITIZING



- Fuel Efficiency Program
- Preventive Maintenance /AHM
- Irregular Operations
- Air Navigation Charges
- ...

TEAM

UKRAINE
INTERNATIONAL
AIRLINES



**Project Leader –
Chief Engineer**

Engineering

Pilots

MCC


Procurement

IT

Finance

THE ROADMAP

Increasing value



* definitions from Honeywell presentation

1ST PHASE - RESULTS



- ✓ **XX** critical impacts on flight safety
- ✓ **XX** AOG
- ✓ **XX** MEL items (flight delays)

were avoided on E190 with only Descriptive/Diagnostic Analytics & Condition Monitoring within 1,5 years

Assumed cost of delay** = 1996,8 USD and cost of AOG = 10 920 USD

**based on average length of delay (company data) and average cost of delay per seat (based on industry data)

NEXT STEPS

- Setup the business case
- Get connectivity for online
- Upgrade Aircraft software
- Setup analytical software
- Update internal processes

CLOSING THE LOOP




- Setup completed Oct 2018
- CAS/CMC Information
- Systems Trend Information


1. SINGLE-BLEED OPERATIONS




DMIs



Days



Costs reduction, \$



2. ENGINE FADEC




Full Authority Digital Electronic Control System controls the operation, performance and efficiency characteristics of the engine through full authority control over the entire engine fuel metering unit, variable stator vanes, operability bleed valve, T2 sensor heater, thrust reverser actuation, engine starting, ignition and also providing engine limit protection during ground starts.

2. ENGINE FADEC

- Engine FADEC 1 (no dispatch) \Leftrightarrow FADEC 2
- 7 days both worked properly
- A new fault message appeared (FIM executed \rightarrow wire and sensor both ok, so only FADEC according to FIM)
- Solution – to replace FADEC?

2. ENGINE FADEC

T1.2 Sensor



GENERAL DESCRIPTION

The temperature indicating system sensors provide temperature data of the engine air inlet, compressor air inlet, compressor discharge, HPT (High Pressure Turbine) case shroud, and LPT (Low Pressure Turbine) stage two nozzle segment. The FADEC uses these information to control the engine.

- The T 1.2 sensor is a dual-element RTD (Resistance Temperature Device) mounted in the flow stream, in front of the fan and above the engine centerline, with one element hardwired to each FADEC channel.

- Reviewed and decided to replace sensor
- ~2k \$ vs ~ 50-60k \$

3. APU FAIL



CAS/CMC Information | Systems Trend Information

From: 05/01/2019 To: 06/20/2019 Show Hidden Messages


Search: DEGR Apply New Messages

Dispatch	Messages	Fault Code	Severity	Date/Time	Status	Phase	Flight #	Possible Solutions
MNT	APU OIL PRESSURE SNSR DEGRADED	49935214APU		05/02/2019 05:51:28	INACTIVE	PREFLIGHT	P5711	FIM
CAS	APU FAIL			05/02/2019 05:50:17	ACTIVE	PREFLIGHT		FIM
MNT	APU OIL PRESSURE SNSR DEGRADED	49935214APU		05/02/2019 05:50:17	ACTIVE	PREFLIGHT		FIM

Reset Status

MODEL

EMBRAER 190
MSN
0589
LOAD
25.7
LDI VERSION
V14.1





- Failure of oil pressure sensor
- Failure of APU FADEC
- Defective HARNESS

TASK 49-93-00-810-801-A

Degradation of APU Oil Pressure Sensor Circuit

A. General

(1) This task is for fault code:

FAULT CODE	FAULT DESCRIPTION
49935214APU	APU OIL PRESSURE SNSR DEGRADED

(2) After completion of the troubleshooting, put the aircraft back to its initial configuration.

B. Fault Description

(1) This maintenance message gives an indication that the oil-pressure-sensor circuit is defective.

(2) The FADEC senses a fault in the oil pressure sensor and sends a fault message to the CMC.


(3) This failure is latched on the APU FADEC. To confirm the fault, it is necessary to turn the APU master switch to the OFF position and then operate the APU ([AMM TASK 49-10-00-910-801-A/200](#)).

C. Probable Causes

(1) Failure of OIL PRESSURE SENSOR ([AIPC 49-93-03](#)) ([AMM MPP 49-93-03/401](#)).

(2) Failure of AUXILIARY POWER UNIT (APU) FADEC ([AIPC 49-61-01](#)) ([AMM MPP 49-61-01/401](#)).

(3) Defective HARNESS ([WM 49-41-50](#)) ([WM 49-71-50](#)).




3. APU FAIL



- Sensor was switched EMC \Leftrightarrow EMB (problem occurred and sensor was replaced)
- APU FADEC was switched (100% not the problem)
- After this EMC 10 days was okay, then fault was reported again
- Decision was to replace APU Wire (at ~100k \$)
- Additional troubleshooting was performed and decision to replace sensor (~12k \$) first was made
- And it worked!

4. BLEED FAIL




- “Bleed 1 fail” message
- HPSOV (High-stage pressure shut-off valve)
- Checked FHDB

4. BLEED FAIL

Main	SAS5536	1000,219,0,0,ACTIVE,03/11/2019 10:03:04,3,2,PREFLIGHT,BLEED 1 FAIL,CAUTION,...
Main	SAS5537	1000,219,344,2681,ACTIVE,03/11/2019 10:03:04,3,2,PREFLIGHT,BLEED 1 FAIL,CAUTION,PRI HX IN TEMP SNSR (PK1)/WRG,21515061AM1,Internal Hardware
Main	SAS5751	1000,219,0,0,INACTIVE,03/11/2019 10:05:14,3,2,PREFLIGHT,BLEED 1 FAIL,CAUTION,...
Main	SAS6022	1000,219,0,0,ACTIVE,03/12/2019 14:51:41,4,7,APPROACH,BLEED 1 FAIL,CAUTION,...
Main	SAS6023	1000,219,935,2523,ACTIVE,03/12/2019 14:51:41,4,7,APPROACH,BLEED 1 FAIL,CAUTION,LH HPSOV (CLOSED) [C2]/WRG FAULT,36111103AM2,Internal Hardware
Main	SAS6024	1000,219,934,2868,ACTIVE,03/12/2019 14:51:41,4,7,APPROACH,BLEED 1 FAIL,CAUTION,LH HPSOV (CLOSED) [C2]/WRG [A],36111106AM2,Internal Hardware
Main	SAS6027	1000,219,0,0,INACTIVE,03/12/2019 14:52:04,4,7,APPROACH,BLEED 1 FAIL,CAUTION,...
Main	SAS6033	1000,219,0,0,INHIBITED,03/12/2019 14:56:34,4,8,ROLL OUT,BLEED 1 FAIL,CAUTION,...
Main	SAS6034	1000,219,935,2523,INHIBITED,03/12/2019 14:56:34,4,8,ROLL OUT,BLEED 1 FAIL,CAUTION,LH HPSOV (CLOSED) [C2]/WRG FAULT,36111103AM2,Internal Hardware
Main	SAS6040	1000,219,0,0,ACTIVE,03/12/2019 14:56:47,4,8,ROLL OUT,BLEED 1 FAIL,CAUTION,...
Main	SAS6041	1000,219,935,2523,ACTIVE,03/12/2019 14:56:47,4,8,ROLL OUT,BLEED 1 FAIL,CAUTION,LH HPSOV (CLOSED) [C2]/WRG FAULT,36111103AM2,Internal Hardware
Main	SAS6060	1000,219,0,0,INACTIVE,03/12/2019 15:51:31,4,2,PREFLIGHT,BLEED 1 FAIL,CAUTION,...
Main	SAS11866	1000,219,0,0,ACTIVE,03/18/2019 16:05:31,28,2,PREFLIGHT,BLEED 1 FAIL,CAUTION,...
Main	SAS11867	1000,219,344,2681,ACTIVE,03/18/2019 16:05:31,28,2,PREFLIGHT,BLEED 1 FAIL,CAUTION,PRI HX IN TEMP SNSR (PK1)/WRG,21515061AM1,Internal Hardware
Main	SAS12278	1000,219,0,0,INACTIVE,03/18/2019 16:09:59,28,2,PREFLIGHT,BLEED 1 FAIL,CAUTION,...
Main	SAS16189	1000,219,0,0,ACTIVE,03/24/2019 16:14:36,58,2,PREFLIGHT,BLEED 1 FAIL,CAUTION,...
Main	SAS16206	1000,219,0,0,INACTIVE,03/24/2019 16:18:31,58,2,PREFLIGHT,BLEED 1 FAIL,CAUTION,...

4. BLEED FAIL



- Apparently there were multiple EICAS & maintenance messages, some resets (not during acceptance flight though)
- Situation was reported to lessor
- Valve at lessor's cost (~30k \$)

IS THE LOOP REALLY CLOSED?

- Procurement, Logistics, Stock
- Analytics
- Ownership
- Promotion
- Value
- Scale

DISCOVERIES ON THE WAY



FINAL TEARDOWN REPORT			
Customer	AERFIN LTD	Cust PO	R51289
		Operator PO	
Input Part	5913840	Input Serial	A1136
		Qty	1.000
Output Part	5913840	Output Serial	A1136
		Workscope	INSPECT
Cust Part		Cust Serial	
Description	POSITION SENSOR UNIT	Removal Code	
Aircraft		Failure Date	
Incoming NSN	N/A	Engine Type	
		Tail No	
		Outgoing NSN	N/A
Date Rec'd	05/09/2019	Quote Date	05/22/2019
		Accept Date	05/29/2019
Ship Date		DOM	
		Last Order Date	12/13/2018
Sales Order	7024846	Work Order	43110700
		Notification	303361097
Measuring Point:			
Serial #	CSN	TSN	CSO
CSR	TSO	TSR	TSI
CSI	TSMI	CSMI	CSCPI
TSCP			
OUT A1136	UNKNOWN	UNKNOWN	UNKNOWN
	UNKNOWN	UNKNOWN	UNKNOWN
	UNKNOWN	UNKNOWN	UNKNOWN
	UNKNOWN	UNKNOWN	UNKNOWN
	0.00	0	0
	UNKNOWN	UNKNOWN	UNKNOWN
	UNKNOWN	UNKNOWN	UNKNOWN
Customer Reason for Return			
EICAS ADVISORY MSG SLAT LO RATE AFTER POWER UP. CREW 3LC NOT READABLE			
Certification Type			
Dual Release 8130-3			
Configuration IN			
Configuration OUT			
Preliminary Inspection			
CMM Reference			
ECR Flag? (Y/N)			
NO			
Incoming Functional Test Performed?(Y/N)			
YES			
Incoming Functional Test Failed? (Y/N)			
NO			

- “slat lo rate” EICAS message - Slat position sensor was removed and ordered
- New one was installed but problem remained
- After continuous t/s sensor was replaced once again – now successfully

DISCOVERIES ON THE WAY



Now we are paying more attention to:

- Certificates
- Warranties
- Stock levels

ARE WE REALLY PREVENTIVE?



MNT	BYPASS VLV (CLSD)(PK2)(C2)VRG	21516300AM2	07/27/2019 04:23:01	INACTIVE	CLIMB	PS804	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C2)VRG	21516300AM2	07/27/2019 04:17:24	ACTIVE	TAKE OFF	PS804	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C2)VRG	21516300AM2	07/27/2019 04:08:40	ACTIVE	TAXI	PS804	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/26/2019 17:21:54	INACTIVE	CLIMB	PS803	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/26/2019 17:15:19	ACTIVE	TAKE OFF	PS803	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/26/2019 17:10:07	ACTIVE	TAXI	PS803	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C2)VRG	21516300AM2	07/26/2019 10:49:44	ACTIVE	TAXI	PS485	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/26/2019 08:13:43	INACTIVE	CLIMB	PS485	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/26/2019 08:01:21	ACTIVE	TAKE OFF	PS485	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/26/2019 07:56:17	ACTIVE	TAXI	PS485	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/25/2019 04:38:32	ACTIVE	ROLL OUT	PS86	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C2)VRG	21516300AM2	07/25/2019 03:49:49	INACTIVE	CLIMB	PS86	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C2)VRG	21516300AM2	07/25/2019 03:48:50	ACTIVE	TAKE OFF	PS86	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C2)VRG	21516300AM2	07/25/2019 03:48:05	ACTIVE	TAXI	PS86	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/24/2019 14:48:30	ACTIVE	TAXI	PS486	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C2)VRG	21516300AM2	07/24/2019 11:54:31	INACTIVE	PREFLIGHT	PS486	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/24/2019 07:54:01	INACTIVE	CLIMB	PS485	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/24/2019 07:48:55	ACTIVE	TAKE OFF	PS485	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/24/2019 07:48:13	ACTIVE	TAXI	PS485	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/24/2019 05:52:02	ACTIVE	PREFLIGHT		FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/24/2019 05:35:37	INACTIVE	PREFLIGHT		FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/24/2019 05:17:26	ACTIVE	TAXI	PS844	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/23/2019 17:23:40	INACTIVE	CLIMB	PS843	FIM
MNT	BYPASS VLV (CLSD)(PK2)(C1)VRG	21516300AM1	07/23/2019 17:14:15	ACTIVE	TAKE OFF	PS843	FIM

- Maintenance msg "Bypass vlv closed" appeared on 23.07.2019. No EICAS msg.
- Decision was taken to replace filter of pack bypass valve
- Problem was resolved 3 days later with no DMI, and no FL restrictions


ARE WE REALLY PREVENTIVE?




MNT	AFT TRIM BYP VLV (OPEN) [C2]/WRG	21627210AM2	08/29/2019 08:03:51	INACTIVE	CRUISE	PS151	FIM
MNT	AFT TRIM BYP VLV (OPEN) [C2]/WRG	21627210AM2	08/29/2019 08:00:33	ACTIVE	CRUISE	PS151	FIM
MNT	AFT TRIM BYP VLV (OPEN) [C1]/WRG	21627210AM1	08/27/2019 11:12:07	ACTIVE	TAXI	PS702	FIM
MNT	AFT TRIM BYP VLV (OPEN) [C1]/WRG	21627210AM1	08/26/2019 09:33:44	INACTIVE	CRUISE	PS802	FIM
MNT	AFT TRIM BYP VLV (OPEN) [C1]/WRG	21627210AM1	08/26/2019 09:19:44	ACTIVE	CLIMB	PS802	FIM
MNT	AFT TRIM BYP VLV (OPEN) [C1]/WRG	21627210AM1	08/15/2019 00:54:51	INACTIVE	CLIMB	PS7112	FIM
MNT	AFT TRIM BYP VLV (OPEN) [C1]/WRG	21627210AM1	08/15/2019 00:47:39	ACTIVE	CLIMB	PS7112	FIM

- 15.08.2019 maintenance msg “aft trim air vlv open position”, no EICAS msg or any complaints for air conditioning system
- According to FIM – the only solution is to replace valve, and it was ordered
- On 26.08.2019 second Maint msg noted, also high temperature in aft cabin was recorded

ARE WE REALLY PREVENTIVE?

1  **Work Step** added by [MKOAN1](#) on 26.Aug.2019 10:20

UNABLE TO CONTROL TEMPERATURE DURING FLIGHT IN AFT CABIN, TEMP IS 34 DEG CEL.
PACK 2 FAIL MSG AFTER LANDING.
FAULT CODE: 21627052AM2
Description Sign [MKOAN1](#)

 **Action** performed by [MKOAN1](#) on 26.Aug.2019 10:40

DEFECT CARRIED FORWARD IAW ERJ-190 MEL ITEM 21-51-00-A CAT "C" ITEM REV.04-1.
DMI #046363/2 RAISED, TILL 05 SEP 2019.

LIMITATION: FLIGHT IS CONDUCTED AT OR BELOW FL 310.
Performed Sign [MKOAN1](#)
Inspection Sign [MNOIG](#)

- DMI was open
- The valve already arrived by then
- Due to aircraft availability (schedule) the valve was replaced on 29.08.2019 and problem was resolved


RESULTS

Our expert assumption for predictive accuracy is:

> 90%

- Reduced number of AOGs and delays, DMIs
- Improved troubleshooting (time & quality)
- Increased reliability and availability of the aircraft

SUMMARY



- Passion
- Hard work
- Constant challenge



UR-EMA	LH HPSOV closed	REF FAN BUILT LED LIGHTS	MAU 2 QUORA FAULT	FLAP LD RATE
12.07.2017	OK	OK	4545119PCM	OK
13.07.2017	OK	OK	4545119PCM	2753000LACE
14.07.2017	OK	OK	4545119PCM	OK
15.07.2017	OK	OK	4545119PCM	OK
16.07.2017	OK	OK	OK	OK
17.07.2017	OK	OK	OK	OK
18.07.2017	3611110SAM1	OK	4545119PCM	OK
19.07.2017	OK	OK	OK	OK
20.07.2017	OK	OK	OK	OK
21.07.2017	OK	OK	OK	OK
22.07.2017	OK	OK	4545119PCM	OK
23.07.2017	OK	OK	4545119PCM	OK
24.07.2017	OK	5212211P55 (Cruise)	OK	OK
25.07.2017	OK	5212211P55 (Cruise)	OK	OK
26.07.2017	OK	OK	OK	OK
27.07.2017	OK	OK	OK	OK
28.07.2017	OK	OK	4545119PCM	OK
29.07.2017	OK	OK	4545119PCM	OK
30.07.2017	OK	5212211P55 (Cruise)	OK	OK
31.07.2017	OK	OK	4545119PCM	OK
01.08.2017	OK	OK	OK	OK
02.08.2017	OK	OK	OK	OK
03.08.2017	OK	5212211P55 (Cruise) need	4545119PCM	2753000LACE (APPROACH)
04.08.2017	OK	OK	4545119PCM	OK
05.08.2017	OK	OK	OK	OK
06.08.2017	OK	OK	OK	OK
07.08.2017	OK	OK	OK	OK
08.08.2017	OK	OK	OK	OK
09.08.2017	OK	4545119PCM + ECAS AVION MAU 2A FAULT Getackr LD was repaired line WFO 889893	OK	OK
10.08.2017	OK	5212211P55 (Cruise)	OK	OK
11.08.2017	OK	OK	OK	OK
12.08.2017	OK	5212211P55 (Cruise)	OK	OK
13.08.2017	OK	5212211P55 (Cruise)	OK	OK
14.08.2017	OK	OK	OK	OK
15.08.2017	OK	OK	OK	OK



Fleet Monitoring
FHDB Decoder

Sort By:
MOST CRITICAL FIRST - CMC

PS151

UR-EMD

(🔊) 00:09

UKBB → EPHK

PS57E

UR-EME

(🔊) 00:51

N/A → N/A

PS471

UR-EMB

(🔊) 00:04

UKBB → L5ZH

PS3TM

UR-EMA

(🔊) 00:15

UKBB → L5GG

PS845

UR-EMC

(🔊) 00:51

UKBB → LOWW

CAS/CMC Information

From: 10/11/2018 To: 10/16/2018 Show

Search:

Dispatch Messages

- ! CAS RAT FAIL
- TAXIING IN
- LIFT OFF
- ! CAS RAT FAIL
- TAXIING OUT
- PARKED
- TAXIING IN
- LIFT OFF
- TAXIING OUT

MODEL

EMBRAER 190

MSN

0602







LOAD

25.7

LDI VERSION

V14.1

JUST KEEP THEM GREEN!

 PS486	 PS472	 PS172	 PS702	 PS152	 PS036	 PS845
UR-EMD 00:05	UR-EMA 00:05	UR-EME 00:08	UR-EMF 00:16	UR-EMC 00:37	UR-EMG 01:07	UR-EMB 03:29
LSGG → UKBB	LSZH → UKBB	ESSA → UKBB	LTBJ → UKBB	EFHK → UKBB	UKLL → UKBB	UKBB → LOWW

UKRAINE
INTERNATIONAL
AIRLINES

