



15<sup>th</sup> Maintenance Cost Conference  
Athens, Greece  
18-19 September 2019

**“Science @ MCC”**

**Dr. Stefano Laureti**<sup>1</sup>

**Mr. Michael Stamm**<sup>2</sup>, **Mr. Tommaso Seresini**<sup>3</sup>, **Dr. Helge Pfeiffer**<sup>3</sup>,  
**Prof. Pietro Burrascano**<sup>4</sup>, **Prof. Marco Ricci**<sup>1</sup>

<sup>1</sup> DIMES, University of Calabria, Rende (CS) Italy

<sup>2</sup> Brussels Airlines, Belgium

<sup>3</sup> KU Leuven, Belgium

<sup>4</sup> Department of Engineering, University of Perugia, Italy

# Presentation Outline

- **“The NDTonAIR” project**
- **Investigated applications**
  - Ultrasonic Inspection
    - ☞ Wing Gear Rib 6 Crack in the A33F
  - Active Thermography
    - ☞ Water ingress
    - ☞ RR Air Intake Noise Panel
    - ☞ Loose rivets
- **Future works and Conclusions**

# The NDTonAIR Project



## Beneficiaries (Recruiting & Training):

**Univ. Perugia (IT) – Coord. Prof P. Burrascano**  
**Brussels Airlines (BE) – Mr J. Reynaert**  
**CEA-List (FR) – Dr D. Premel, Dr C. Rebaud**  
**Fraunhofer IKTS (DE) – Dr B. Koehler**  
**Kaunas KTU (LT)- Profs R.Kazis, L. Mazeika, E. Jasiuniene**  
**KU Leuven (BE) – Profs M.Wevers , C. Gloriuex, H. Pfeiffer**  
**Univ. de Nantes (FR) – Prof G. Berthiau**  
**Univ. of Newcastle (UK) – Prof G.Y. Tian**  
**RECENDT (AT) – Dr P. Burgholzer**  
**TWI Limited (UK) – Dr S. Soua**  
**Univ. of Warwick (UK) – Profs D.Hutchins ,S. Dixon**

## Partners (Secondment & Training):

**Univ. Calabria (IT) – Chair of the  
supervisory board Prof M. Ricci  
Manager Dr S. Laureti**  
**Univ. Cassino (IT)**  
**COTESA (GE)**  
**Dresden TU (GE)**  
**FH Upper Austria (AT)**  
**JKU Linz (AT)**  
**MDP (IT)**  
**Univ. Paris Saclay (FR)**  
**SIEMENS (GE)**  
**X-Phase(IT)**

# The NDTonAIR Project



[www.ndtonair.eu](http://www.ndtonair.eu)



3.8 M€




4 years




15 PhD/ESR's



- Development of new NDT & SHM methods
- Promotion of (non-)scientific collaboration
- Training of aviation NDT experts



Foster  
academic & industrial  
collaboration



# Investigated applications

- **Ultrasonic Inspection**

- ➔ **Wing Gear Rib 6 Crack  
in the A33F**

- Active Thermography

- ➔ Water ingress

- ➔ RR Air Intake Noise  
Panel


- ➔ Loose rivets

# Wing Gear Rib 6 Crack in the A33F - AIRBUS

➤ **Standard maintenance procedure: REMOVAL OF LANDING GEAR**


## Assumptions:

- Crack propagation from the inside;
- Initial starting point of crack between FWD and AFT Bush (see picture below);
- Small cracks only detected with Eddy Current after removal of Landing Gear;
- Visual inspection only enough when crack propagated through the whole structure;




# Wing Gear Rib 6 Crack in the A33F - AIRBUS

## Standard maintenance procedure



- Inspection of moved bushes
- If grease and/or bushes are moving, then:
  - Landing Gear (LG) removal;
  - Dye penetrant inspection;

## Proposed Inspection Method: Ultrasonic Phased Array



- Inspection of moved bushes
- If grease and/or bushes moved:
  - ~~landing gear removal~~
  - PAUT inspection


# Wing Gear Rib 6 Crack in the A33F - AIRBUS

➤ **Standard maintenance procedure: REMOVAL OF LANDING GEAR → Time consuming!!**




**PROPOSED SOLUTION: Phased-Array Ultrasound without landing gear removal!**



Case #1: Inspection from the front face of the Rib




Phased-Array Probe




Our proposal: Pulse-compression Phased-Array system



Case #2: Inspection from the front face of the Rib




Case #3: Inspection from the inner and/or outer surface of the Rib



**Advantages over standard Phased-array systems:**

- The use of advanced input signals and processing (coded signals and pulse-compression) provides a higher detectability!





# Wing Gear Rib 6 Crack in the A33F - AIRBUS

 **PROPOSED SOLUTION: Pulse-compression Phased-Array Ultrasonic testing without landing gear removal!**



- LG replacement: **c.a. 25 k€**
- 6 weeks **unscheduled Aircraft on ground (AOG)** 1000 k€ pax compensation for Brussel Airlines
- 750 k€ wet leased A/C

**→ c.a. 1.75 M€ of saving per effected A/C**

## Actual state of the investigation:

1. Received Rib from Lufthansa Technik
2. Performing FE simulations
3. Performing measurements on REAL Rib!
4. Go to the hangar and measure in REAL environment!

**NOTE: the aim is NOT to replace current inspection methodology but to provide a handy tool for more frequents inspections!!**

**SAFETY**

# Investigated applications

- Ultrasonic Inspection
  - ✎ Wing Gear Rib 6 Crack in the A33F
- **Active Thermography**
  - ✎ **Water ingress**
  - ✎ RR Air Intake Noise Panel
  - ✎ Loose rivets

# Water Ingress detection with Thermography

**AIRBUS**

CUSTOMIZATION	AIRCRAFT TYPES	DOCTYPES	REVISION DATE	TITLE	TAIL NUMBER - MSN - FSN
	A330 A340	NTM	01- Apr-2019	51-10-25-290-801-A01 - General Procedure for Thermography Inspection to detect Trapped Water in Honeycomb Structures mounted Vertically for Ambient Temperatures between 10° C and 35° C (50° F and 95° F) - Procedure A	

**\*\* ON A/C MSN ALL**

TASK 51-10-25-290-801-A01

General Procedure for Thermography Inspection to detect Trapped Water in Honeycomb Structures mounted Vertically for Ambient Temperatures between 10° C and 35° C (50° F and 95° F) - Procedure A

1. Task Supporting Data

A. Area of Applicability

This procedure provides the general procedure for inspection of honeycomb sandwich structures with FRP layers and honeycomb core. There is a limitation to thicker top skins and honeycomb identification (See [FIGURE 51-10-25-991-001](#)).

This procedure is valid for all undisturbed honeycomb sandwich structures in the following configuration (See [FIGURE 51-10-25-991-001](#)):

- FRP top and bottom layers
- Layer thickness L = 0.4 mm – 1.5 mm (0.016 in – 0.059 in) (layer on the side to be inspected)
- Honeycomb:
  - Honeycomb height H = 30 – 40 mm (1.18 in – 1.575 in) and cell size between 4.8 mm and 6.4 mm (0.189 in and 0.252 in)
  - Minimum amount of fluid:
    - At honeycomb height H = 30 mm (1.18 in) = > 6 ml fluid
    - At honeycomb height H = 40 mm (1.575 in) = > 6 ml fluid

**NOTE:** Repaired areas are not testable

Repaired areas (outer skin repairs and core repairs) are normally not visible at the rudder structure. For identification of the repaired areas see the test results of the thermography inspection according to task 55-40-50-290-801.


B. Description of Possible Damage

(1) Different Damage Types

- Honeycomb cells containing more than 50% of trapped fluid per cell in areas equal to or greater than 200 mm<sup>2</sup> (0.310 in<sup>2</sup>) in size (See [FIGURE 51-10-25-991-002](#)).
- The filled honeycomb cells must lie next to each other (See [FIGURE 51-10-25-991-002](#)).
- The minimum distance or extent from all edges must be 15 mm (0.591 in) (See [FIGURE 51-10-25-991-002](#)).

C. Job Set-Up Information

- (1) Tooling:



**NOTE:**

L = LAYER THICKNESS  
H = HONEYCOMB HEIGHT

MATERIAL	WEIGHT	WRENCH SIZE
HONEYCOMB	kg/m <sup>3</sup>	mm (in)

L\_NT\_511025\_1\_0010101\_01\_01


Figure 51-10-25-991-001-A (SHEET 1) - Inspection Area  
\*\* ON A/C MSN ALL

# Water Ingress detection with Thermography

## 1. Task Supporting Data

### A. Area of Applicability

This procedure provides the general procedure for inspection of honeycomb sandwich structures with FRP layers and honeycomb core. There is a limitation to thicker top skins and honeycomb identification (See [FIGURE 51-10-25-991-001](#)).



## Limitations:

- Detectability of water ingress is limited to “relatively-thin” composite parts.
- Low detection capability - both standard heat modulation scheme (step-heating or long-pulse) and heat sources (air heater) are employed.
- The data is not saved, and the movement is left to the human being as well as the data assessment.

# Water Ingress detection with Thermography





## Proposed solutions:

- **Employing suitable heat sources (low power LED chips or halogen lamps), advanced heat modulation scheme and post-processing techniques for:**

**1) enhancing water ingress detection for thicker composite samples;**


**2) reducing power consumption.**

**400W LEDs chips Thermography Setup** An example of coded-modulated modulation:






The effectiveness of the proposed methodology has been proved for CFRP inspection!

“Pulsed Thermography”



“Barker&Step”



# Water Ingress detection with Thermography


## Proposed solutions:

- Employing suitable heat sources (low power LED chips or Halogen Lamps), advanced heat modulation scheme and post-processing techniques for:

1) enhancing water ingress detection for thicker composite samples;

2) reducing power consumption.


### 400W LEDs chips Thermography Setup




!!!  
6 kJ flash head lamps (or even stronger) must be used with care!! Coded-modulated LED chips + Pulse-compression provides the same results, and even better in some cases, but with no risks for the user

!!!

WITHOUT  
Pulse-compression



WITH  
Pulse-compression



# Water Ingress detection with Thermography

## Pulse-compression Thermography example



*“Resurrezione” – Andrea Mantegna*

*Accademia Carrara, Bergamo*


Paintings on panel, end of 15<sup>th</sup> century

Recently re-attributed to Andrea Mantegna, as the upper half of a two-part paintings together with “Discesa di Cristo al limbo”

Measurements made on-site during the restoration process

Many indications from time-analysis of thermograms: wood grain structure, nails & grouts, cracks, preparation layer

# Water Ingress detection with Thermography



Sold for 30 milion € !



# Water Ingress detection with Thermography


Real



Image



Abs



Angle



$T = 0.10 \text{ s}$

# Water Ingress detection with Thermography

Real



Image



Abs



Angle



$T = 0.35 \text{ s}$

# Water Ingress detection with Thermography

Real



Image



Abs




Angle



$T = 0.60 \text{ s}$

# Water Ingress detection with Thermography

$T = 0.60 \text{ s}$




# Investigated applications


- Ultrasonic Inspection
  - ☞ Wing Gear Rib 6 Crack in the A33F
- **Active Thermography**
  - ☞ Water ingress
  - ☞ **RR Air Intake Noise Panel**
  - ☞ Loose rivets

# Investigated applications: RR Air Intake Noise Panels

## RR Air Intake Noise panels inspection (once per year)



- 10 h of work
- Hand-written records
- Accuracy is very subjective



- Inspection time: c.a. 30 min
- Automated inspection
- Objective Tomographic & Digital data
- Pixel Accuracy



- **95% time reduction for inspection!!!**
- Higher detection capability & more frequent inspections:
  - big repairs → small repairs (-200 k€)
  - Less likely to ground A/C!!!
  - No spare part of inlet needed (70 k€/month) (rented)

**SAFETY**

**95 % time saving → part of A-check?**

# Investigated applications

- Ultrasonic Inspection
  - ☞ Wing Gear Rib 6 Crack in the A33F
- **Active Thermography**
  - ☞ Water ingress
  - ☞ RR Air Intake Noise Panel
  - ☞ **Loose rivets**

# Loose Rivets

## MANDATORY MANDATORY MANDATORY

ATA SYSTEM: 52


**TITLE: DOORS - AFT CARGO COMPARTMENT DOOR - INSPECT STRUCTURE FOR CRACKS AND LOOSE/LOST/SHEARED RIVETS**

- Mandatory inspection of AFT Cargo Door
- Inspect visually Loose/Lost/Missing Fasteners
  - (a) Do a Detailed inspection of the outer skin and inner surfaces of the AFT Cargo Compartment Door frame heads area at beam 1 for cracks, loose, sheared or missing fasteners at the subsequent locations in accordance with **NTM 51-90-00** and as shown on [Fig. A-GBFAA Sheet 01](#), [Fig. A-GBGAA Sheet 01](#), [Fig. A-GBHAA Sheet 01](#) and [Fig. A-GBJAA Sheet 01](#):

DESC 51-90-00-001 CONF A - General

### 1. General

- A. Visual inspection procedures are among the simplest and most economical of all the nondestructive testing methods.
- B. Optical instruments can be used to assist the inspection by magnifying discontinuities that are too small to be seen by the unaided eye.
- C. Other instruments may also be used to inspect areas where the access is difficult.





# Loose Rivets

## MANDATORY MANDATORY MANDATORY

ATA SYSTEM: 52


TITLE: DOORS - AFT CARGO COMPARTMENT DOOR - INSPECT STRUCTURE FOR CRACKS AND LOOSE/LOST/SHEARED RIVETS

- Mandatory inspection of AFT Cargo Door
- Inspect visually Loose/Lost/Missing Fasteners
- Repetitive inspection ever 550 FC (flight cycle)

If no crack is found during the Special Detailed Inspection	Replace fasteners	Before next flight	None
	Repeat inspection	None	550 FC


2,5 FC/day -> every 8 month!!!

- Costs:



# Loose Rivets

Task 525023-832-848-001: Inspection	
Identify the Part Number of the AFT Cargo Compartment Door	0.50
Do a Check and if necessary adjust the AFT Cargo Compartment Door Hook Gaps (only at first inspection)	1.00
Do a Detailed Inspection (DET) of the AFT Cargo Compartment Door Frame Fork Areas	2.00
Do A Detailed Inspection (DET) of the AFT Cargo Compartment Door Frame Head Areas	2.00
Do a Special Detailed Inspection (SDI) of the AFT Cargo Compartment Door Frame Fork Areas	6.00
Do a Special Detailed Inspection (SDI) of the AFT Cargo Compartment-Door Frame Head Areas	6.00
Repair the AFT Cargo Compartment Door Frame Fork Area Fastener Holes by Bushing	4.00
Replace the AFT Cargo Compartment Door Frame Fork	10.00
Do the Adjustment of the AFT Cargo Compartment Door Hook Gaps	5.00
Tests	1.00
Close-Up	1.00
<b>TOTAL MANHOURS</b>	<b>39.50</b>
<b>ELAPSED TIME (HOURS)</b>	<b>39.50</b>



# Loose Rivets

## MANDATORY MANDATORY MANDATORY

ATA SYSTEM: 52


TITLE: DOORS - AFT CARGO COMPARTMENT DOOR - INSPECT STRUCTURE FOR CRACKS AND LOOSE/LOST/SHEARED RIVETS

- Mandatory inspection of AFT Cargo Door
- Inspect visually Loose/Lost/Missing Fasteners
- Repetitive inspection ever 550 FC (flight cycle)


If no crack is found during the Special Detailed Inspection	Replace fasteners	Before next flight	None
	Repeat inspection	None	550 FC

2,5 FC/day -> every 8 month!!!




- Costs: 40 hours/door/aircraft/every eight month
- BEL: 21 A/C x 2 doors x 8/12 month → 28 weeks




# Loose Rivets





- FLIR SC7000
- Glued PZT
- Sweep: 15-25 kHz
- 10 images averaged






# Loose Rivets




# Loose Rivets



# Loose Rivets



# Loose Rivets










# Conclusions

1. Immense need for innovative inspection methods
2. Science & Safety
3. Science & Safety & Cost Reduction
4. Need for more automatic detection method

## RESUME OF THE PROPOSED METHODS:

- Pulse-compression Phased Array for Rib inspection without LG removal
- Pulse-compression Thermography for water and noise panel inspection
- Ultrasonic-stimulated Thermography for loose rivets



This research has received  
funding from the "NDTonAIR" project under the action:  
H2020-MSCA-ITN-2016- GRANT 722134.  
[www.ndtonair.eu](http://www.ndtonair.eu)



# Thanks for your attention!

[stefano.laureti@unipg.it](mailto:stefano.laureti@unipg.it)  
[lauretistefano@gmail.com](mailto:lauretistefano@gmail.com)  
[www.ndtonair.eu](http://www.ndtonair.eu)

**KU LEUVEN**

